

Generating In-process Stock and Checking Validity

I-DEAS® Tutorials: Milling Projects and Turning Projects

In this tutorial, you'll learn how to generate in-process stock. In-process stock is a representation of the stock after the tool cuts away material for each operation. Your stock appears on the workbench as if it were "in the process" of being machined.

You'll also modify the setup assembly and update the toolpath to the changes.

Learn how to:


- generate in-process stock
- modify a setup assembly
- check validity

Before you begin...

Prerequisite tutorials:

- all tutorials under the Modeling Fundamentals menu
- Introduction to Generative Machining
- Building a Setup Assembly

Retrieve the model file that you created in the Building a Setup Assembly tutorial.



Model File Name: ncsetup



Make sure you're in the following application and task:




Application: Manufacturing



Task: Generative Machining

Set your units to inches.



Inch (pound f)

Recovery Point



Warning!

If you're prompted by I-DEAS to save your model file, respond:




Save only when the tutorial instructions tell you to—not when I-DEAS prompts for a save.

If you make a mistake at any time between saves and can't recover, you can reopen your model file to the last save and start over from that point.

Hint


To reopen your model file to the previous save, press Control-Z.

In the next steps, you'll turn on in-process stock calculations and create a volume clear operation. After you process the toolpath, you'll notice that the stock instance reflects the cutting passes. In particular, the tool avoids the clamp that overlaps the pocket and leaves material under it.



What: Enable in-process stock calculations for the setup.

How:



NC Job Planning form



Setup-1




Setup Specification form



Enable In-Process Stock Calculations—On



Dismiss

 Don't close the NC Job Planning form.

What: Modify the opgroup and create a volume clear operation.

How:

NC Job Planning form



OpGroup-1

OpGroup Specification form



Operation Selection form




Category: Milling



Type: Volume Clear



Create


 Don't close the Operation Specification form.

What: Name the operation, then pick the surfaces composing the pocket.


How:

Operation Specification form

Name: Clear Pocket



double-click on the surface to select the pocket




Things to notice

All surfaces related to the bottom surface you selected are highlighted.



Stock Specification form

OK

 Don't close the Operation Specification form.

What: Create a .25 inch end mill.

How:

Operation Specification form



Cutting Tool Specification – Mill form

Identifier: .25 Endmill

Press the Tab key to move to the next field.

I-DEAS Warning form



OK



Style: End Mill

Holder To Tip Dist: 2.5


Max Depth of Cut: 1.5

Cutter Diameter: .25

Nose Radius: 0



OK

 Don't close the Operation Specification form.

What: Define the step between each cutting pass as 60 percent of the tool diameter.

How:

Operation Specification form



Machining Parameters form



Stepover Distance (on): 60

Things to notice

You'll accept the default cut pattern of *Spiral Out* and the cut type of *Climb*. You use *Spiral Out* so the tool will start the cuts inside the pocket and make the last pass along the walls.



OK

 Don't close the Operation Specification form.

What: Generate the toolpath.


How:

Operation Specification form



Recovery Point


 *File*
Save



Things to notice


The in-process stock reflects the volume of material removed by the tool. Material is even left where the tool overlaps the pocket. The tool follows in a spiral-out cut pattern to machine the selected surfaces.

In the next steps, you'll modify the setup assembly by moving the clamp that blocks the pocket. You'll do this by deleting the existing centerline-to-centerline constraint and then creating a new centerline-to-centerline constraint. You do not want to delete the face-to-face constraint.




What: Delete the centerline-to-centerline constraint.

How:




1 Pick anywhere on the clamp.



 Don't close the Assembly Relations Browser form.

Assembly Relations Browser form



2 Centerline constraint



I-DEAS Warning

 OK


 Dismiss

Recovery Point


 File
Save

What: Move the clamp by creating a new centerline-to-centerline constraint.


How:



- 1** CL1 (centerline of clamp)
- 2** CL13 (centerline of hole)



Result



Things to notice

The clamp is positioned in the second hole and no longer obscures the pocket.


Recovery Point

 *File*
Save

When you modify a job after generating a toolpath, the software warns you about the effects of those changes with a validity flag:


- +, or valid—the job entity is up-to-date and doesn't require changes
- –, or invalid—the job entity may transfer out-of-date information to the CL file, or the CL file itself is out-of-date
- o, or user validated—an invalid operation has been accepted and doesn't require further modification

If you recall, you just modified the setup assembly by moving a clamp. In the next steps, you'll review the validity flags and reprocess the toolpath to make the operation valid.



What: Check the validity flags to determine the effects of your changes to the setup assembly.

How:



NC Job Planning form



Clear Pocket

Things to notice

The “-” next to the operation indicates it may be invalid. An operation can become invalid if you change the selected surfaces, the machining parameters, the cutting tool, or the setup. An operation is also marked invalid if you haven’t created a toolpath for it yet.



Check *I-DEAS List*.


The I-DEAS List suggests reprocessing the toolpath to update the operation.




Dismiss

What: Reprocess the toolpath.

How:



I-DEAS Warning form




Things to notice

The tool cleans up the material that was once covered by the clamp.

What: Review the validity flags.

How:



NC Job Planning form


Things to notice

The “+” validity marker by the operation indicates the toolpath has been updated.

 *Dismiss*

What: Look at the assemblies and parts in the bins.

How:



Manage Bins form

Things to notice

The software creates a new bin called In-Process Stock to contain the in-process stock models after each toolpath. For this operation, you created an in-process stock model called Stock-ips1 (double-click *Setup Tutorial Job...*). The software saves each stock model so it can be used for the following cutting operation.



Dismiss

Tutorial wrap-up

You've completed the Generating In-process Stock and Checking Validity tutorial.